







MEYLE[®]
Products

MEYLE No. 300 311 2909/HD
Reference No. 31 12 0 006 482
31 12 1 093 707

Control arm bushings to fit BMW E38, E39



  Problem	  Solution
<p>High dynamic strain causes leakage of the hydro-liquid.</p>	<p>Replacing the hydro mount with a full rubber mount</p>
<p>Effect</p>	<p>Advantage</p>
<ul style="list-style-type: none"> • Vibration in the steering • Reduced driving comfort 	<p>No leakage possible and significant longer lifetime with more driving comfort</p>

MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • Lo2.2006
Merkurring 111 • 22143 Hamburg • Germany
contact@meyle.com • www.meyle.com