



MEYLE[®]
Products

MEYLE No.

Referenz No.

Bushing
Control arm, right
Control arm, left

300 311 2104/HD
316 050 0008/HD
316 050 0007/HD

31 12 6 769 715
31 12 6 769 718
31 12 6 769 717



Control arm bushing to fit BMW E53 (X5)



as OE

Problem

High dynamic strain causes leakage of the hydro-liquid

Effect

- Vibration in the steering
- Reduced driving comfort



Solution

Replacing the hydro mount with a full rubber mount

Advantage

No leakage possible and significant longer lifetime with more driving comfort



Control arm, right - MEYLE No.: 316 050 0008/HD

MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • L05.2007
Merkurring 111 • 22143 Hamburg • Germany
contact@meyle.com • www.meyle.com