







MEYLE[®]
Products

| | MEYLE No. | Reference No. |
|--------------------|-----------------|---------------|
| Bushing | 014 033 0115/HD | 203 333 10 14 |
| Control arm, left | 016 050 0031/HD | 203 330 39 11 |
| Control arm, right | 016 050 0032/HD | 203 330 40 11 |

Bushing, control arm to fit Mercedes W203, S203, C203, R171, C209, A209



|   Problem |   Solution |
|--|---|
| <p>Leakage of hydro fluid due to high dynamic strain and small bonding surface</p> | <p>Hydro mount replaced by an optimised full-rubbermount with a larger bonding surface</p> |
| <p>Effect</p> | <p>Advantage</p> |
| <ul style="list-style-type: none"> • Steering vibration • Impaired driving safety | <ul style="list-style-type: none"> • Leakage no longer possible • Significantly longer service life • More safety • More driving comfort |

MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • L11.2008
Merkurring 111 • 22143 Hamburg • Germany
contact@meyle.com • www.meyle.com