



HD-Stabilizer links



As OE

Problem

Intense strain causes wear and stress of the components

Effect

Premature failure of the ball joint
Noise from the front axle

MEYLE-HD

Solution

- Enlarged ball diameter (22mm)
- Reinforced link rod
- MEYLE high-tech grease
- Wear resistant blue plastic seat

Advantage

Significantly longer service life thanks to reinforced design

as OE



MEYLE version

