






	MEYLE No.	Reference No.
Bushing	014 033 0024/HD	140 333 18 14 26
Repair kit	014 033 0015/HD	140 330 82 07

Bushing, control arm to fit Mercedes W140, C140



 Problem	 Solution 
<p>Leakage of hydro fluid due to high dynamic strain and small bonding surface</p>	<p>Hydro mount replaced by an optimised full-rubber mount with a larger bonding surface</p>
Effect	Advantage
<ul style="list-style-type: none"> • Steering vibration • Impaired driving safety 	<ul style="list-style-type: none"> • Leakage no longer possible • Significantly longer service • More safety • More driving comfort



MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • Lo7.2008
 Merkurring 111 • 22143 Hamburg • Germany
 contact@meyle.com • www.meyle.com