

**MEYLE**<sup>®</sup>  
Products

	MEYLE No.	Reference No.
Control arm, left	016 050 0056/HD	901 330 24 07
Control arm, right	016 050 0054/HD	901 330 25 07
Ball joint, left + right	036 010 0113/HD	901 333 12 27
Control arm bushing	034 033 0004	901 333 02 14

## Control arm to fit Mercedes Sprinter, VW LT II

as OE

### Problem

Intense strain of the control arm due to overloading of the vehicle and fast driving

### Effect

- Worn out ball joints
- Damaged rubber mounts
- Noise from the front axle




### Solution

- Exchangeable ball joints with improved quality
- Wear-resistant plastic seats in the ball joint (developed in cooperation with **Lufthansa Technik Intercoat GmbH**)
- MEYLE high-tech grease
- Delivery incl. nut
- Exchangeable rubber mounts

### Advantage

Control arm with long service life



Exploded drawing ball joint

**Lufthansa Technik**  
Intercoat

**MEYLE - Miles in Motion**

© MEYLE Products® - Wulf Gaertner Autoparts AG • Lo7.2007  
Merkurring 111 • 22143 Hamburg • Germany  
contact@meyle.com • www.meyle.com